

Oil Field Environmental Incident Summary

Incident: 20190913172842 **Notice:** 9/13/2019 17:28 **Occurred:** 9/12/2019 14:15

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: HA-NELSON A-152-95- 3427H-1

Field Name: HAWKEYE

Well File #: 18245

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 152 95 34

Location Description: 47.934736,-102.818878

Submitted By: Kathleen Kangas

Received By:

Contact Info: Kathleen Kangas
1501 MCKINNEY
HOUSTON TX 77010

Affected Medium: Topsoil

General Land Use: Cultivated

Near. Occupied Bldg: 0.6 Mile

Nearest Water Well: 0.6 Mile

Type of Incident: Equipment Failure

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.3	Barrels			1.3	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 10/9/2019

Written Report Recd: 10/10/2019

Risk Evaluation:

oil sheen running offsite due to excessive rain

Areal Extent:

Offsite area approx 285ft X 4 ft of very light sheen calculated to be 6.1295 gallons.

Potential Env. Impacts:

impacts to surface vegetation/soil. Impacts appear to the north of the facility.

Action Taken/Planned:

The well was immediately shut in and the site glass was isolated. SROs and EHS staff were notified. Boom was brought it to block the sheen from running off site. All offsite impacts will be remediated.

Wastes Disposal Location:

An approved waste disposal facility.

Other Agencies Involved:

Updates

Date: 9/16/2019 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to equipment failure was not contained according to the report. More follow-up needed.

Updated Volumes and Contaminant None at the time of this update

Date: 9/16/2019 **Status:** Correspondence **No Further Action:**

Author: O'Gorman, Brian

Notes:

An email was received from the company contact giving an update on amount released off the well pad (6.1295 gallons). Email added to the incident folder. More followup needed.

Updated Volumes and Contaminant None at the time of this update

Date: 12/31/2020 **Status:** Correspondence - More Follow-up Required **No Further Action:**

Author: DeVries, Taylor

Notes:

A site visit is recommended. Further follow-up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 12/29/2021 **Status:** Inspection - More Follow-up Required **No Further Action:**

Author: DeVries, Taylor

Notes:

Inspection Date: 12/29/2021

Arrived on location at 1125. Snow cover present during the time of the inspection. Further follow-up is needed in the summer months.

Photos were taken and can be found in the incident folder.

Updated Volumes and Contaminant None at the time of this update

Date: 7/28/2022 **Status:** Inspection - No Action Required **No Further Action:**

Author: Suess, Bill

Notes:

Inspected the site on 7/25/2022. Observed the perimeter of the well pad. The vegetation appeared healthy and consistent with the surrounding area. No further action is warranted.

Updated Volumes and Contaminant None at the time of this update