

# Oil Field Environmental Incident Summary

**Incident:** 20190913215351      **Notice:** 9/13/2019    21:53    **Occurred:** 9/13/2019    12:30

**Responsible Party:** EQUINOR ENERGY LP

**Well Operator:** EQUINOR ENERGY LP

**Well Name:** HOUSTON 11-2 1H

**Field Name:** BUFORD

**Well File #:** 24833

**Facility ID #:**

**County:** WILLIAMS

**Twp Rng Sec Qtr:** 152 104 11

**Location Description:**

**Submitted By:** Jimmy Dickson

**Received By:**

**Contact Info:** Jimmy Dickson  
6300 BRIDGE POINT PKY, BLDG 2  
SUITE 100  
AUSTIN TX 78730

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

<b>Brine</b>	50	Barrels	50	Barrels		
--------------	----	---------	----	---------	--	--

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

Operator Shut In well and pumping unit and LOTO, Called Supervisor. Clean up will start as soon as road conditions improve. Work order will be put in to replace corroded piping.

**Wastes Disposal Location:**

To be determined

**Other Agencies Involved:**

## **Updates**

---

**Date:** 9/16/2019      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release remained on location according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update