

# *Oil Field Environmental Incident Summary*

**Incident:** 20190915124836      **Notice:** 9/15/2019    12:48    **Occurred:** 9/15/2019    08:00

**Responsible Party:** SCOUT ENERGY MANAGEMENT LLC

**Well Operator:** SCOUT ENERGY MANAGEMENT LLC

**Well Name:** SFTU 5-19

**Field Name:** FRYBURG

**Well File #:** 12181

**Facility ID #:**

**County:** BILLINGS

**Twp Rng Sec Qtr:** 139 100 19

**Location Description:**

**Submitted By:** Josh Morel

**Received By:**

**Contact Info:**  
 Josh Morel  
 906 Highway 85 N  
 Belfield ND 58622

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 1 Mile

**Nearest Water Well:** 1 Mile

**Type of Incident:** Tank Leak

**Release Contained:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1.5	Barrels	1	Barrels		
<b>Brine</b>						
<b>Other</b>			10	Barrels		

**Oth Rel. Contaminant:** We used 10 barrels of fresh water to clean up.

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None

**Areal Extent:**

NA

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

Washed and sucked up spill

**Wastes Disposal Location:**

Tank on location

**Other Agencies Involved:**

## **Updates**

---

**Date:** 9/16/2019      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release remained on location according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update