

# *Oil Field Environmental Incident Summary*

**Incident:** 20191031111637      **Notice:** 10/31/2019 11:16      **Occurred:** 10/30/2019 10:45

**Responsible Party:** XTO ENERGY INC

**Well Operator:** XTO ENERGY INC

**Well Name:** FARM 44X-7

**Field Name:** HOFFLUND

**Well File #:** 16490

**Facility ID #:**

**County:** WILLIAMS

**Twp Rng Sec Qtr:** 154 95 7

**Location Description:** On and off pad. Off pad to the east approximately 28' x 48'

**Submitted By:** Kaylan Dirkx

**Received By:**

**Contact Info:**  
 Kaylan Dirkx  
 110 WEST 7TH STREET  
 FORT WORTH TX 76102

**Affected Medium:** Topsoil

**General Land Use:** Pasture

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Treater Popoff

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.2	Barrels	0.1	Barrels		
<b>Brine</b>	0.2	Barrels	0.1	Barrels		

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None- small burned vegetation area and mist (approximately 19 gallons released of oil/pw fluid)

**Areal Extent:**

East of pad 48' x 28' (burn area)

**Potential Env. Impacts:**

Minimal-burned vegetation area (48' x 28'). De-minimis amount of oil/pw mist off pad to the east.

**Action Taken/Planned:**

Scale inside separator was the cause of the plugging, it was removed and impacted material will be cleaned up. Landowner requested off site (not burned) vegetation be mowed, bagged and disposed of.

**Wastes Disposal Location:**

R360-Prairie

**Other Agencies Involved:**

## Updates

---

**Date:** 10/31/2019      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release impacted areas off location. Follow-up is required.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 11/15/2019      **Status:** Inspection - Vegetation Check      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

Arrived on location at 1200.

No observation of a burned area on the east side of the well pad nor any hydrocarbon staining. At the time of the inspection it was very foggy.

Received confirmation samples from responsible party. These samples show no impact to the soils that were affected by the release. Further follow up is needed in summer for a vegetation check. Report can be found in report folder.

Photos were taken and can be found in the report folder.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 5/1/2020      **Status:** Correspondence - Vegetation Check      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

A summer 2020 vegetation check is recommended for this incident.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 8/20/2020      **Status:** Inspection - No Action Required      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

Inspection Date: 8/20/2020

Arrived on location at 1700. The area of concern has natural vegetation growing very nicely. The trees looks healthy and growing as well. No further action needed at this time.

Photos were taken and can be found in the report folder.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 9/4/2020

**Status:** Correspondence - No Action Required

**No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

Taylor DeVries sent a No Further Action letter dated September 4, 2020.

**Updated Volumes and Contaminant** None at the time of this update