

# Oil Field Environmental Incident Summary

**Incident:** 20191101131222      **Notice:** 11/1/2019      13:12      **Occurred:** 10/31/2019      16:45

**Responsible Party:** EQUINOR ENERGY LP  
**Well Operator:** EQUINOR ENERGY LP  
**Well Name:** GUNDERSON 15-22 #3H  
**Field Name:** BANKS  
**Well File #:** 22578  
**Facility ID #:**  
**County:** MCKENZIE  
**Twp Rng Sec Qtr:** 152 98 15  
**Location Description:**  
**Submitted By:** Jimmy Dickson  
**Received By:**  
**Contact Info:** Jimmy Dickson  
6300 BRIDGE POINT PKY, BLDG 2  
SUITE 100  
AUSTIN TX 78730

**Affected Medium:** Topsoil  
**General Land Use:** Pasture

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Fire  
**Release Contained:** Unknown  
**Reported to NRC:** No

<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None

**Areal Extent:**

25 square feet of burned Grass.

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

Operator put out fire immediately. Fire department was also dispatched by a passerby on highway. By time they got to pad, the fire was out. No fluid was released. Think was just a small ember of scale or rust possibly that ignited grass

**Wastes Disposal Location:**

N/A

**Other Agencies Involved:**

Local Fire Department

**Updates**

---

**Date:** 11/4/2019      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** Lund, Dylan

**Notes:**

According to incident summary, a fire set the surrounding grass on fire. Follow-up necessary.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 11/5/2019      **Status:** Inspection - No Action Required      **No Further Action:**

**Author:** Torgerson, Brad

**Notes:**

On 11/5/2019 at 3:10 pm - Cloudy and 34 Degrees F - I visited the Equinor Energy LP - Gunderson 15 - 22 #3H production facility. I walked the perimeter of the facility and couldn't find any signs of a fire or oil stained vegetation. No further follow-up appears to be necessary.

**Updated Volumes and Contaminant**    None at the time of this update