

# *Oil Field Environmental Incident Summary*

**Incident:** 20191110171127      **Notice:** 11/10/2019 17:11      **Occurred:** 11/10/2019 10:00

**Responsible Party:** Wisco INC  
**Well Operator:** CONTINENTAL RESOURCES, INC.  
**Well Name:** PALMER FEDERAL 10-25H  
**Field Name:** HAYSTACK BUTTE  
**Well File #:** 35382  
**Facility ID #:**  
**County:** MCKENZIE  
**Twp Rng Sec Qtr:** 149 98 25  
**Location Description:** next to lease road going into location  
**Submitted By:** chansy wolff  
**Received By:**  
**Contact Info:** chansy wolff  
13916 55th St NW  
Williston ND 58801

**Affected Medium:** Topsoil  
**General Land Use:** Badlands Terrain

**Near. Occupied Bldg:**  
**Nearest Water Well:**

**Type of Incident:** Tank Leak

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	20	Gallons	20	Gallons		

**Oth Rel. Contaminant:** Diesel from truck

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

NA

**Areal Extent:**

5 x 15 feet

**Potential Env. Impacts:**

topsoil

**Action Taken/Planned:**

trucks need to be chained up in icy conditions

**Wastes Disposal Location:**

tbd

**Other Agencies Involved:**

## Updates

---

**Date:** 11/12/2019      **Status:** Reviewed - Follow-up Required

**No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

Release, due to a tank leak, was not contained according to the report. More followup needed.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 11/18/2019      **Status:** Inspection - Vegetation Check

**No Further Action:**

**Author:** Schmitt, Bryan

**Notes:**

Inspection Date: 11/14/2019

Time: 3:15 pm CT

Truck rollover occurred on the north side of lease road at the bottom of a hill. A diesel smell was present in the area. No visual sign of diesel fuel was present and there was no sheen on nearby water. Two soil samples, analyzed for DRO, GRO, and Group 190, were taken to determine if there are any impacts in the rollover area. Coordinates for the samples are: 47.70678, -103.18166 and 47.70682, -103.18.182. Pictures taken.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 7/10/2020      **Status:** Inspection - No Action Required

**No Further Action:**

**Author:** Suess, Bill

**Notes:**

Inspected the site on 7/9/2020. The spill occurred on the access road leading to the well pad. Walked the entire access road and no adverse environmental impacts associated with this release were observed. The vegetation along the access road appears healthy and consistent with the surrounding area. No further action is warranted.

**Updated Volumes and Contaminant**    None at the time of this update