Oil Field Environmental Incident Summary

Responsible Party: FOUNDATION ENERGY MANAGEMENT, LLC **Well Operator:** FOUNDATION ENERGY MANAGEMENT, LLC

Well Name: KLANDL 43-26

Field Name: MONDAK
Well File #: 7824

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 148 105 26

Location Description: The spill was contained within secondary containment on the Klandl tank

battery (earthen berms).

Submitted By: Alyssa Beard

Received By:

Contact Info: Josh Raburn

5057 KELLER SPRINGS RD,

SUITE 650

ADDISON TX 75001

Affected Medium: Well/Facility Soil

General Land Use: Cultivated
Near. Occupied Bldg: 3300 Feet

Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained: Yes - On Facility Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 40 Barrels 35 Barrels

Other

Oth Rel. Contaminant: Production water with a skim of oil.

Date Inspected:

Clean Up Concluded: Written Report Recd: Risk Evaluation:

None

Areal Extent:

Spill contained within earthen berm.

Potential Env. Impacts:

Potential impact to soil.

Action Taken/Planned:

NDIC called Foundation on November 15th to alert to a tank overflow in progress. Foundation sent a pumper to the location to assess the situation. A vac truck was called on 11/15 to remove standing fluids from within the berms. Power to the unit has been turned off and the flowline closed.

Wastes Disposal Location:

Waiting to hear from Powerfuels on the amount removed (above is an estimate) and disposition location. Further details will be provided on the follow-up spill report.

Other Agencies Involved:

Updates

Date: 11/19/2019 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the release of brine was contained to the well pad. NDIC takes

oversight.

Updated Volumes and Contaminant None at the time of this update