

Oil Field Environmental Incident Summary

Incident: 20200208130046 **Notice:** 2/8/2020 13:00 **Occurred:** 2/8/2020 09:45

Responsible Party: Denbury Onshore LLC
Well Operator: DENBURY ONSHORE, LLC
Well Name: CHSU BW 21-26SH 16
Field Name: CEDAR HILLS
Well File #: 15293
Facility ID #:
County: BOWMAN
Twp Rng Sec Qtr: 131 106 26 NE NW
Location Description: 21-26SH16
Submitted By: Steve Hansen
Received By:

Contact Info: Roy Madsen
5320 LEGACY DR
PLANO TX 75024-3127

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg: 8900 Feet
Nearest Water Well: 4900 Feet
Type of Incident: Equipment Failure
Release Contained: No
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other	20	Barrels
--------------	----	---------

Oth Rel. Contaminant: Source Water

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

none

Areal Extent:

250 feet long by 1.5 feet wide

Potential Env. Impacts:

none

Action Taken/Planned:

Repair and test line

Wastes Disposal Location:

If anything needs to be disposed of it will go to LMS

Other Agencies Involved:

Updates

Date: 2/10/2020 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Suess, Bill

Notes:

This incident was not fully contained on the well pad. Follow-up is required.

Updated Volumes and Contaminant None at the time of this update

Date: 2/11/2020 **Status:** Inspection - More Follow-up Required **No Further Action:**

Author: Stockdill, Scott

Notes:

Arrived on location 12:21 2/11/2020.

No sign of release due to recent snowfall. Check site in spring to ensure proper cleanup.

More follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 5/18/2020 **Status:** Inspection - More Follow-up Required **No Further Action:**

Author: Stockdill, Scott

Notes:

Arrived on location 1:47 5/18/2020.

No sign of contaminants or contamination. Contact company regarding the exact location of the release.

More follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 5/29/2020 **Status:** Correspondence - More Follow-up Required **No Further Action:**

Author: Stockdill, Scott

Notes:

Email from responsible party detailing the location and flow path where the spill occurred.

"... Ran off over location over by the Kimray between the wells to the NE of location and followed the Injection line Right away. Here is a snap shot of the location with direction of flow. ..."

Full email and attachments in the incident folder.

More follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 8/3/2021

Status: Inspection - No Action Required

No Further Action:

Author: Martin, Russell

Notes:

7/29/2021 at 13:27, on location. Walked area indicated by RP, vegetation appears uniform. No further follow-up needed.

Updated Volumes and Contaminant None at the time of this update