

# Oil Field Environmental Incident Summary

**Incident:** 20200216133321      **Notice:** 2/16/2020 13:33      **Occurred:** 2/16/2020 02:00

**Responsible Party:** ENERPLUS RESOURCES USA CORPORATION

**Well Operator:** ENERPLUS RESOURCES USA CORPORATION

**Well Name:** MUSKRAT 150-94-04B-09H

**Field Name:** SPOTTED HORN

**Well File #:** 29528

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 151 94 33

**Location Description:**

**Submitted By:** Joey Sheeley

**Received By:**

**Contact Info:** Josh Ruffo  
US BANK TOWER  
950 17TH ST STE 2200  
DENVER CO 80202

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

<b>Brine</b>	30	Barrels				
--------------	----	---------	--	--	--	--

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None.

**Areal Extent:**

N/A

**Potential Env. Impacts:**

None.

**Action Taken/Planned:**

The valve was closed and a clean-up crew was dispatched.

**Wastes Disposal Location:**

Approved disposal facility

**Other Agencies Involved:**

BLM, MHA Nation, TAT Environmental