## Oil Field Environmental Incident Summary

Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: MOSS 149-93-21C-22H-LL

Field Name: MANDAREE

**Well File #:** 35762

Facility ID #:

County: DUNN

**Twp Rng Sec Qtr:** 149 93 21

**Location Description:** 

**Submitted By:** Joey Sheeley

Received By:

Contact Info: Josh Ruffo

**US BANK TOWER** 

950 17TH ST STE 2200 DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak
Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 10 Barrels 1 barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 2/16/2020 Written Report Recd: 2/28/2020

Risk Evaluation:

None

Areal Extent:

N/A

Potential Env. Impacts:

None

Action Taken/Planned:

The connection was closed and a clean-up crew was dispatched.

Wastes Disposal Location:

Approved disposal facility

Other Agencies Involved:

BIA, BLM, MHA Nation, TAT Environmental

## **Updates**

Date: 2/18/2020 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Suess, Bill

Notes:

Incident was contained on a well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update