

General Environmental Incident Summary

Incident: 10626 **Notice:** 12/6/2020 1358 **Occurred:** 12/5/2020 0330

DEM Incident No:

No Further Action:

Responsible Party: Marathon Petroleum

County: Stark

Twp Rng Sec Qtr: 139 97 15

Lat Long + Method: 46.85861 -102.89420 Interpolation from map

Location Description: 3815 116TH Ave SW
Dickinson, ND 58601

Submitted By Info: Tonya Woolery
HES Professional
3815 116th Ave SW
Dickinson ND 58601

Received By Info:

Contact Info: Tonya Woolery
3815 116th Ave SW
Dickinson ND 58601

Affected Medium: 03 - soil

Near. Occupied Bldg: 1 Miles

Type of Incident: Tank Leak

Release Contained: Yes

Reported to NRC: No

Contaminant: F037 Petroleum refinery primary oil/water/solids separation sludge

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

A valve on a API sludge dewatering valve froze and split. During warm temperatures fluid (listed F037 waste) thawed and flowed onto a permeable surface. Volume of the release has been tentatively calculated at 70 gallons.

Risk Evaluation:

No immediate risk of explosive atmosphere or immediate health hazards.

Potential Env. Impacts:

Likelihood of impacts to surface or ground water is possible but unlikely. Spill clean-up is underway.

Action Taken/Planned:

The valve was replaced and the line was capped. Clean-up activities are underway.

Wastes Disposal Location:

All waste will be sent to Clean Harbors for disposal.

Other Agencies Involved:

Updates

Date: 12/6/2020 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary this release impacted the surrounding area. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 12/28/2020 **Status:** Inspection - Vegetation Check

Author: DeVries, Taylor

Notes:

Inspection Date: 12-28-2020

Arrived at provided GPS coordinates. Inspected a riser and a few areas around that riser. Did not observe any hydrocarbon staining. There are some bare patches by the riser that are covered in snow. Unsure if these bare spots relate to this release. Further follow-up will be made with the responsible party to confirm inspection was in the correct location.

Photos were taken and can be found in the report folder.

Updated Volume: None at the time of this update

Date: 5/17/2021 **Status:** Correspondence - No Action Required

Author: Crowdus, Kory

Notes:

Spoke to contact about incident and it was verified the release has been cleaned. Release was to a gravel surface which was scraped and new material was brought in. Photos were provided by company contact and can be found in the report folder. No further follow-up needed.

Updated Volume: None at the time of this update