General Environmental Incident Summary

			•	
Incident: 5294	Notice: 12/20/2016	Occurred:	12/19/2016	1900
DEM Incident No:			No Further Ad	ction: 🗸
Responsible Party:	Sloulin Field International Air	port		
County:	Williams			
Twp Rng Sec Qtr:	154 101 11			
Lat Long + Method:	48.17637 -103.63180	Interpolation from map)	
Location Description:	408 Airport Rd. Williston, ND 58801			
Submitted By Info:	Andy McDonald			
	Montana-Dakota Utilities Co			
	400 N 4th St			
	Bismarck ND 58501			
Received By Info:				
Contact Info:				
	421 Airport Rd.			
	Williston ND			
Affected Medium:	09 - other			
Near. Occupied Bldg:	100 Feet			
Type of Incident:	Padmount Transformer Oil S	pill		
Release Contained:	Yes			
Reported to NRC:	No			
Contaminant:	Mineral Oil (<1ppm PCB per nameplate)			
Volume of Release:	60 gallons			
Duration of Release:				
Agriculture Related:	No			
EPA Extremely				
Hazardous Substance:	No			
Number of Fatalities:	0			
Number of Injuries:	0			
Cause of Incident:				

A padmount transformer was hit while the airport was removing snow from the area, which caused oil to leak from the unit.

Risk Evaluation:

None

Potential Env. Impacts:

There should be no impacts once the oil is removed from the snowmelt.

Action Taken/Planned:

A boom was placed around the spill perimeter and the oil was absorbed by snow on the airport pavement. The contaminated snow is being removed and placed into holding containers until the oil can be separated from the water. Absorbent material was placed on the pavement after the snow was removed to collect any residual oil.

Wastes Disposal Location:

The wastes will be disposed of at an approved facility.

Other Agencies Involved:

Updates

Date: 12/20/2016 Status: Reviewed - Follow-up Required

Author: Schiermeister, Robin

Notes:

The release involved mineral oil so this report has been forwarded to the Division of Waste Management. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 12/21/2016 *Status:* Correspondence

Author: Tintes Schiwal, Emily

Notes:

A representative from MDU reported that airport staff hit their transformer with a vehicle while removing snow from the runway. The spilled oil contaminated the surrounding snow, so a berm was put in place and crews gathered up all of the snow with visible oil. The airport has a spill cleanup team, so they will be handling the cleanup. It was relayed to MDU that the airport has a stormwater permit with the Department and that they will need to follow the parameters within that permit while working on this case. He said he would relay that information to the airport and will be getting back to me with photos and more information.

Updated Volume: None at the time of this update

Date: 12/29/2016 Status: Correspondence

Author: Tintes Schiwal, Emily

Notes:

A photo of the unit that was hit is in the corresponding folder. The PCB test results came back at 0ppm and the test is also in the corresponding folder.

Updated Volume: None at the time of this update