# General Environmental Incident Summary

*Incident:* 5295 *Notice:* 12/21/2016 1332 *Occurred:* 12/21/2016 0158

DEM Incident No: No Further Action:

Responsible Party: Tesoro Logistics

County: Stark

Twp Rng Sec Qtr: 140 97 19 NW NW

Lat Long + Method: 46.93394 -102.84930 Navigation quality GPS

Location Description: From the intersection of Hwy 22 and I94 travel 2.5 north to 33rd St SW

(truck bypass), turn west on 33rd St SW traveling 2.8 miles to the incident.

**Submitted By Info:** Mark Glaser

Tesoro - Employee 2972 108S Ave SW Dickinson ND 58601

Received By Info:

**Contact Info:** 

2972 108S Ave SW Dickinson ND 58601

Affected Medium: 03 - soil

Near. Occupied Bldg: 1443 Feet

Vehicle Assi

Type of Incident: Vehicle Accident

Release Contained: Yes
Reported to NRC: Unknown
Contaminant: crude oil
Volume of Release: 70 barrels

**Duration of Release:** 

Agriculture Related: No

**EPA Extremely** 

Hazardous Substance:NoNumber of Fatalities:0Number of Injuries:0

Cause of Incident:

A Tesoro transport driver was traveling on iced roads when the vehicle left the driving surface entering the road ditch. The truck over turned causing release of crude oil to ground.

### Risk Evaluation:

none

## Potential Env. Impacts:

Crude oil impacts to soil and snow. There are no impacts to surface or ground water.

#### Action Taken/Planned:

Local law enforcement, recovery vehicle, and spill remediation contractor were contacted and are onsite for support.

## Wastes Disposal Location:

Permitted and approved waste disposal facility such as R360 Environemental

# Other Agencies Involved:

NDDES, Local Law Enforcement

## **Updates**

Date: 12/21/2016 Status: Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

According to the report, 70 barrels of crude oil was released onto a road ditch due to a vehicle accident. A field inspector has been notified and will visit the site tomorrow. More follow-up needed.

Updated Volume: None at the time of this update

Date: 12/22/2016 Status: Inspection

Author: Striebel, Ivana

#### Notes:

Location is north of Dicksinson, on 33rd St SW, ~3 miles west of Hwy 22. On-site at 5:20 pm. Contractor was excavating and piling up contaminated soil for transport. Spill is located between two roads with a culvert that runs north. Culvert is located ~10 ft west of the spill. Spoke to Jake Tompkins (SM Fencing), who said that the road had been recently constructed, because of this the soil in the ditch where the spill happened had not yet been able to establish vegetation and the soil had not yet settled. When the semi tipped, it broke through the frost layer and infiltrated directly to soil where the fluids followed cracks and fissures in the soil. The contractors were following the spill through these cracks and fissures. At the time of inspection there were no standing liquids. Contractor was hoping to have the area cleaned up before the storm that was forecast for the upcoming weekend. Off-site at 6 pm.

**Updated Volume:** None at the time of this update

Date: 11/29/2017 Status: Correspondence

Author: Martin, Russell

#### Notes:

Received closure report on incident as part of a larger information collection on all currently open Tesoro (now Andeavor) incidents. Report for this incident indicates cleanup is complete. Based on report, no further follow-up required at this time.

**Updated Volume:** None at the time of this update