

General Environmental Incident Summary

Incident: 5331 **Notice:** 3/3/2017 1543 **Occurred:** 2/24/2017 0030

DEM Incident No:

No Further Action: ☒

Responsible Party: Walter Dickson

County: McKenzie

Twp Rng Sec Qtr: 150 95 11 SE SE

Lat Long + Method: 47.81943 -102.79330 Derived from Twn Rng

Location Description: P. Levang 16-11X pad, nearest the P. Levang 14-13-23-24LL well.
Directions: from 73 east
turn right (north) on 102nd Ave NW.
Stay to the left, the road will turn into 103rd Ave NW.
turn left at next intersection. follow to well site.

Submitted By Info: Shawna Dickson
Sick Boy Trucking
91 1st St NW
Killdeer ND 58640

Received By Info:

Contact Info: Walter Dickson
91 1st st nw
killdeer ND 58640

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: diesel spill

Release Contained: Yes

Reported to NRC: No

Contaminant: diesel

Volume of Release: 25 gallons

Duration of Release: 2 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

OVERFLOW. employee, Roger Wilson, was fueling semi, instructed to not walk away from nozzle by his boss, Walter Dickson. Walter continued maintenance on other equipment, went to check on Roger and immediately saw fuel was overflowing. Walter did not see Roger anywhere around. Walter stopped the overflow and found Roger in the truck cab eating. Notified him of the spill.

Risk Evaluation:

no immediate risks

Potential Env. Impacts:

no environmental impacts

Action Taken/Planned:

Walter sucked up the diesel with the vac truck and put diapers down to absorb what was left on the ground. weather halted further cleanup until 03/03/2017. will update of further clean up.

Wastes Disposal Location:

1804 DISPOSAL

Other Agencies Involved:

Updates

Date: 3/7/2017 ***Status:*** Inspection

Author: Torgerson, Brad

Notes:

Visited the spill location on 3/7/2017 - Windy and 15 Degrees F. After discussing the spill particulars on the phone with Walter Dickson, I viewed the NE production location surface area of the QEP Energy Company - P. Levang 16-11X. What appeared to be some fuel stained soil (8' X 8') was observed near the northern area of the facility location. A perimeter berm was noted around the location; thus, it appeared any apparent fuel associated with this incident may not run-off the production location. Further follow-up by the DOH appears to be unnecessary.

Photos were taken and added to the incident folder. Some photos have comments associated with them, which are available using the Image button on the main form.

Updated Volume: None at the time of this update