

General Environmental Incident Summary

Incident: 5332 **Notice:** 3/4/2017 1525 **Occurred:** 3/3/2017 0700

DEM Incident No:

No Further Action:

Responsible Party: Elite Oilfield Services, LLC

County: Williams

Twp Rng Sec Qtr: 155 99 31

Lat Long + Method: 48.20007 -103.45970 Interpolation from map

Location Description: Hwy 1804 E from Williston, N on 126th Ave NW, W on 54th St NW 2.4 miles to spill site.

Submitted By Info: Brian Langford
Manager
301 58th St W
Suite 329
Williston ND 58801

Received By Info:

Contact Info: Jacob Langford
301 58th St W #329
Williston ND 58801

Affected Medium: 03 - soil

Near. Occupied Bldg: 1.14 Miles

Type of Incident: Vehicle Accident

Release Contained: Yes

Reported to NRC: No

Contaminant: Freshwater; also 5 gallons of diesel, motor oil and antifreeze mixture

Volume of Release: 50 barrels

Duration of Release: 1 hours

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Compacted snow on road caused icy situation at turn, truck slid over edge at slow speed at the turn. Tipped over but did not roll.

Risk Evaluation:

None

Potential Env. Impacts:

None

Action Taken/Planned:

HydroVac dispatched to the scene, 4 inches extracted at very small spill location - about 8 ft x 8 ft. Didn't appear that the oil or antifreeze penetrated the compacted snow that was on the road, but we went down a couple inches on the road to be sure.

Wastes Disposal Location:

Will be taken to Secure Disposal (13 Mile Corner in Williston)

Other Agencies Involved:

Local Law Enforcement

Updates

Date: 3/6/2017 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

According to the report, 5 gallons of diesel fuel, motor oil and antifreeze was released during a truck accident. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 3/6/2017 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Notes:

Received call from company contact who wanted to add 50 Barrels of freshwater to the release. Truck was hauling freshwater, some of which leaked out during incident. Further follow-up is required.

Database record has been changed to show the contaminant as freshwater and the volume released as 50 barrels. This was done because the freshwater release had a larger volume than the original contaminant. Report was filed with contaminant specified as 5 gallons of diesel, motor oil and antifreeze. Because of the change of contaminant, the main record was modified. There no mechanism in the update record to indicate a change of contaminant.

Updated Volume: None at the time of this update

Date: 3/7/2017 **Status:** Inspection

Author: Martin, Russell

Notes:

3/7/2017 at 15:19, on location. Called report contact; contact said incident site is at 90-degree curve east of P Bibler wellpad. Truck tipped over on south side of the road. Checked curve; some dirt has been disturbed in the area, but there is no visible staining on ground or snow. No further follow-up required at this time.

Updated Volume: None at the time of this update