

Updates

Date: 3/13/2017 **Status:** Reviewed - Follow-up Required

Author: Martin, Russell

Notes:

Release, due to crack on threads, occurred at a non-E&P exempt facility according to the report. Follow-up is necessary. Based on lat/long, "Hwy 2" given in location description should presumably be "Hwy 23."

Updated Volume: None at the time of this update

Date: 3/20/2017 **Status:** Inspection

Author: Schiermeister, Robin

Notes:

Arrived on site 3-14-2017 at 17:30 CT. It was sunny but cold. The release was contained within the facility building located on site. The release still needs to be cleaned up. No contamination was seen outside the building. No further follow-up is needed. No photos taken.

Updated Volume: None at the time of this update