# **General Environmental Incident Summary**

Incident: 5405	<i>Notice:</i> 5/18/2017 1101 <i>Occurred:</i> 5/16/2017 0445
DEM Incident No:	No Further Action: 🔽
Responsible Party:	Lunderby Trucking LLC
County:	McKenzie
Twp Rng Sec Qtr:	150 96 14
Lat Long + Method:	47.80452 -102.94140 Interpolation from map
Location Description:	Round about at Johnsons Corner. Intersection of Hwy 23 / Hwy 73 / CR 53
Submitted By Info:	Andrew Bradley
	Lunderby Trucking LLC
	12314 County Rd 351
	Sidney MT 59270
Received By Info:	
Contact Info:	Andrew Bradley
	12314 County Road 351
	Sidney MT 59270
Affected Medium:	03 - soil
Near. Occupied Bldg:	401 Feet
Type of Incident:	Vehicle Accident
Release Contained:	Yes
Reported to NRC:	Unknown
Contaminant:	Production / Recycled Fresh Water from drilling.
Volume of Release:	20 gallons
Duration of Release:	3 hours
Agriculture Related:	No
EPA Extremely Hazardous Substance:	Unknown
Number of Fatalities:	0
Number of Injuries:	0
Cause of Incident:	

Truck entered round about at too high of a speed and rolled over. Another trucks was on site shortly to offload the rolled truck. The rolled truck tipped over on the concrete and never left the concrete. Some antifreeze (couple gallons) and some diesel (couple gallons) spilled on the concrete. Some water from the trailer dripped from the top hatch. Most of what dripped out hit the concrete, with a little bit that hit the dirt on the shoulder of the road.

#### Risk Evaluation:

None

### Potential Env. Impacts:

Minimal impacts. No spillage went into any water sources. Minimal water went into soil. About 10 gallons worth of dirt was taken from the side of the road from spilled water.

#### Action Taken/Planned:

Another trucks was on site shortly and hooked up to the rolled truck. This stopped the dripping from the trailer. Floor dry (100 lbs) was spread to absorb the antifreeze, diesel, and water on the concrete. About 2 five gallon buckets of dirt from the shoulder of the road were removed from the water that spilled on the dirt.

### Wastes Disposal Location:

All spilled liquids, absorbent, and dirt were taken to Sorenson SWD

## **Other Agencies Involved:**

State Highway Patrol, Local Fire Department, Local Law Enforcement

# **Updates**

Date: 5/23/2017 Status: Reviewed - Follow-up Required

Author: O'Gorman, Brian

## Notes:

According to the report, 20 gallons of production water was released during a vehicle accident. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 6/29/2017 Status: Inspection

Author: Martin, Russell

# Notes:

6/28/2017 at 18:49, on location. Called report contact to verify location of release due to heavy traffic on this roundabout. Contact indicated NE corner of roundabout was location of accident. No visible staining or visibly impacted vegetation adjacent to NE corner of roundabout. No further follow-up required at this time.

Updated Volume: None at the time of this update