General Environmental Incident Summary

Incident: 5508 **Notice:** 9/8/2017 **Occurred:** 9/8/2017 1130

DEM Incident No: No Further Action:

Responsible Party: Patriot Well Solution

County: McKenzie
Twp Rng Sec Qtr: 150 101 21

Lat Long + Method: 47.80370 -103.61850 Navigation quality GPS

Location Description: 0.5 miles west of Patriot fuels on South side of road in Ditch.

Submitted By Info: David Cordes

Patriot Well Solutions - Field Service Manager

514 22nd Ave NE Williston ND 58801

Received By Info:

Contact Info: David Cordes

514 22nd AVE NE Williston ND 58801

Affected Medium: 03 - soil
Near. Occupied Bldg: 0.5 Miles

Type of Incident: Vehicle Accident

Release Contained: No Reported to NRC: No

Contaminant: ASP-820
Volume of Release: 1 barrels

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities: Number of Injuries: Cause of Incident:

Tire blew on Chemical Van, Box truck. and sent the truck into the opposite lane ditch. It broke the straps holding the totes down and broke one inside that caused the spill

Risk Evaluation:

No risk

Potential Env. Impacts:

No Impact likely

Action Taken/Planned:

Clean Harbors was dispatched to clean up the spill.

Wastes Disposal Location:

Other Agencies Involved:

Local Law Enforcement

Updates

Date: 9/11/2017 Status: Reviewed - Follow-up Required

Author: Crowdus, Kory

Notes:

Release in roadway ditch. Follow-up required.

Updated Volume: None at the time of this update

Date: 9/12/2017 Status: Correspondence

Author: Suess, Bill

Notes:

Received MSDS on ASP-820 from responsible party. Responsible party stated that Clean Harbors is remediating the site and will collect confirmation samples.

Updated Volume: None at the time of this update

Date: 9/13/2017 Status: Reviewed - Follow-up Required

Author: Wax, Pete

Notes:

On site 08:33, clear, calm 64 degrees, nearest pathway to water is highway 85 south ditch. Spill occurred just in the agricultural field on the south side of highway. GPS coordinates are accurate. The there is still moisture and staining on top, along with a hydrocarbon smell. Additionally there are a few vehicle related pieces of metal and rubber at the site. Area disturbed is not substantial at approximately 20' by 30' and appears that it would be a fairly simple task to clean up. A follow-up visit is needed to ensure that the cleanup is accomplished. Off Site 8:50.

Updated Volume: None at the time of this update

Date: 11/28/2017 Status: Inspection

Author: Washek, Sandi

Notes:

Arrived onsite at 4:25pm weather was sunny with temperature of 46 degree F. GPS N47.80453 W 103.61788 located on the south side of HWY 85. An area of about 20 feet by 20 feet has been scraped up and you can see were truck tracks have left the highway. There are still parts of the truck in the ditch, but the area where soil has been scraped is located on top of the ditch next to a field. Will need to contact company to see if clearance soil samples were collected. Additional follow-up needed.

Updated Volume: None at the time of this update

Date: 8/28/2019 Status: Inspection

Author: Washek, Sandi

Notes:

Arrived onsite at 2:10pm; weather was sunny with wind out of the NW at 15 miles/Hr. Temperature of 80 degrees F.

The area of impacted has been cleanup and the truck parts have been removed. You can see in the ditch an area where the grass is not growing due to fresh soil. Appears that the area has been scraped up again. Due to past accidents in the ditch area, no additional follow-up needed

Updated Volume: None at the time of this update