



## **Updates**

---

**Date:** 9/20/2017      **Status:** Reviewed - Follow-up Required

**Author:** Martin, Russell

**Notes:**

Release is within a Oneok facility. Follow-up during the quarterly inspection schedule.

**Updated Volume:** None at the time of this update

---

**Date:** 3/9/2018      **Status:** Correspondence

**Author:** Striebel, Ivana

**Notes:**

2/16/2018 - Received before and after pictures from responsible party. It appears it was scraped up and new fill was added. Release occurred in right-of-way and not onsite. Revisit this site in spring to check for re-vegetation. Follow-up needed.

**Updated Volume:** None at the time of this update

---

**Date:** 9/10/2019      **Status:** Correspondence

**Author:** Suess, Bill

**Notes:**

The site needs to be re-inspected for verification of revegetation.

**Updated Volume:** None at the time of this update

---

**Date:** 12/29/2020      **Status:** Correspondence - Vegetation Check

**Author:** DeVries, Taylor

**Notes:**

A site visit is recommended to assess vegetation growth. Further follow-up is needed.

**Updated Volume:** None at the time of this update

---

**Date:** 5/24/2021      **Status:** Inspection - No Action Required

**Author:** Suess, Bill

**Notes:**

Inspected the site on 5/18/2021. The area has been remediated and no adverse environmental impacts, associated with this release, were observed. No further action is warranted. No photos were taken due to the camera not being intrinsically safe.

**Updated Volume:** None at the time of this update