

General Environmental Incident Summary

Incident: 5570

Notice: 11/8/2017

Occurred: 11/8/2017 1900

DEM Incident No:

No Further Action:

Responsible Party: CHS Inc.

County: Sargent

Twp Rng Sec Qtr: 130 54 7

Lat Long + Method: 46.09336 -97.50852 Interpolation from map

Location Description: corner of 138th Ave SE and 91st St SE. Aprox 3 miles N of Rutland ND

Submitted By Info: Eric Pearson
Cenex Harvest States
4115 27th Ave N
Grand Forks ND 58203

Received By Info:

Contact Info: Eric Pearson
4115 27th Ave N
Grand Forks ND 58203

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Vehicle Accident

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Diesel Fuel

Volume of Release: 15 gallons

Duration of Release: 15 minutes

Agriculture Related: Yes

EPA Extremely Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries:

Cause of Incident:

Tractor with Tanker turning corner and rear fell into ditch rolling vehicle.

Risk Evaluation:

low if any.

Potential Env. Impacts:

low if any

Action Taken/Planned:

Spilled material is being caught in buckets as it drips. Tanker is being pumped out. At first light a better view of any spilled material will be addressed.

Wastes Disposal Location:

approved waste site.

Other Agencies Involved:

Updates

Date: 11/9/2017 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

Release, due to a truck accident, impacted soils along a road ditch. Spoke with the environmental consultant and was asked to what levels the release needed to be cleaned. Also asked for confirmation samples when completed. Once they find a contractor and establish road control, work will commence, possibly today or tomorrow. Emails exchanged and added to the incident folder. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 11/15/2017 **Status:** Inspection

Author: Espe, Brady

Notes:

4:55 p.m. The site is located on the south side of the gravel road in the southeast corner of the intersection. The area has tall vegetation, did not see any surface water. There is a small slough on the northside of the road. Did not see any culverts in this area of the road. There are numerous test holes about the size in diameter of a five-gallon pail and six inches deep, except for test hole 2, which is larger. The test holes have absorbent material in them. Test holes 2 and 3 have standing fuel oil around the absorbent materials. Could smell the diesel. The utilities have been marked. More follow-up required. 49.09480, -97.50860.

Updated Volume: None at the time of this update

Date: 9/4/2019 **Status:** Correspondence - More Follow-up Required

Author: O'Gorman, Brian

Notes:

Incident reviewed and will contact company for reclamation photos and/or confirmation samples. On-site inspection could occur if in vicinity. More follow-up needed.

Updated Volume: None at the time of this update

Date: 7/6/2020 **Status:** Inspection - No Action Required

Author: Crowdus, Kory

Notes:

At location 7/6/2020, at 3:00pm. There is a lot of standing water in the ditch. Vegetation in the area is green and growing. No remaining impacts seen at this time. No further follow-up is required.

Updated Volume: None at the time of this update