

# General Environmental Incident Summary

**Incident:** 5578

**Notice:** 11/26/2017 1830

**Occurred:** 11/26/2017

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** MRL trucking

**County:** McKenzie

**Twp Rng Sec Qtr:** 150 94 9 SW SW NE

**Lat Long + Method:** 47.82730 -102.72240 Interpolation from map

**Location Description:** North on 22 5 miles from mandaree

**Submitted By Info:** Rick Lucas  
4949 162nd Ave NE  
Baldwin ND 58521

**Received By Info:**

**Contact Info:** Rick Lucas  
4949 162nd Ave NE  
Baldwin ND 58521

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:** 2 Miles

**Type of Incident:** Vehicle Accident

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** #2 diesel clear

**Volume of Release:** 700 gallons

**Duration of Release:** hours

**Agriculture Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Number of Fatalities:** 0

**Number of Injuries:** 2

**Cause of Incident:**  
Driver lost control of truck

**Risk Evaluation:**  
No

**Potential Env. Impacts:**  
Soil.

**Action Taken/Planned:**  
Burn around spill. baronko bros. cleaning area.

**Wastes Disposal Location:**

**Other Agencies Involved:**  
State Highway Patrol, Local Emergency Manager

## **Updates**

---

**Date:** 11/27/2017      **Status:** Reviewed - Assigned to Other Agency

**Author:** Martin, Russell

**Notes:**

Release due to vehicle accident. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA. NDDoH inspector will also be visiting site.

**Updated Volume:** None at the time of this update

---

**Date:** 11/27/2017      **Status:** Inspection

**Author:** Washek, Sandi

**Notes:**

Arrived onsite at 3:48pm. Weather was overcast and raining. Temperature of 45 degree F. The site of incident is located on east side of the ditch off Hwy 22, GPS N47.82019 W 102.71436. The path of the diesel impacted the soil next to the pavement then flowed south into the ditch, south through culvert and stopped about 10 feet south of the culvert. Bronco Brothers were onsite removing the impacted roadside soil. 6 truck loads have been removed so far and sent to Secure Energy by Keene, ND. Bronco Brothers also placed a dirt berm in the ditch south of the impacted culvert and a catch basin was placed above the impacted site to catch all the fresh water coming down the ditch. That water is being pumped around the impacted area and south of the culvert too. NDDoH inspector was informed that the Tribal inspector (Milton) had been onsite. Since this is on tribal land they are lead oversight.

**Updated Volume:** 700 gallons