

General Environmental Incident Summary

Incident: 5608

Notice: 1/16/2018

Occurred: 1/15/2018 1525

DEM Incident No:

No Further Action:

Responsible Party: Hiland Crude LLC

County: McKenzie

Twp Rng Sec Qtr: 152 102 24

Lat Long + Method: 47.97731 -103.67650 Navigation quality GPS

Location Description: Alex Terminal, 144441 39th Street NW, Alexander, ND 58831, From Williston head west on US-2, turn left at US-85S continue for 13.4 miles and turn right onto Co Rd 16. Site will be on left hand side in ~0.8 miles.

Submitted By Info: Teresa Merrill
Hiland Crude LLC
11 37th Ave SE, Bldg 29
PO Box 1207
Williston ND 58802

Received By Info:

Contact Info: Teresa Merrill
PO Box 1207
Williston ND 58802

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Tank Overflow

Release Contained: Yes

Reported to NRC: No

Contaminant: Crude Oil

Volume of Release: 3.5 barrels

Duration of Release:

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

MOV failure on crude pipeline divert vessel.

Risk Evaluation:

No immediate risks to human health, or water.

Potential Env. Impacts:

Impacted snow and soil.

Action Taken/Planned:

Operations that arrived on site able to close MOV to stop release. Spill contained in vessel secondary containment. Misting of snow outside containment estimated at ~1.3 gallons. Response companies cleaned up misting and majority of standing oil day of discovery.

Wastes Disposal Location:

Gibson Energy Landfill

Other Agencies Involved:

NDIC

Updates

Date: 1/16/2018 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

Release, due to a tank overflow, was not contained, according to the report. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 1/22/2018 **Status:** Inspection

Author: Schmitt, Bryan

Notes:

Date of Inspection: 1/18/2018, Time: 10:15 AM CST, Temp: 27F

Overflow from a storage tank onsite caused a spill into secondary tank containment. Some oil was not contained in secondary containment and this oil impacted snow and soil near the tank. No impacts were observed off site and a clean up crew was working on the impacted area at the time of inspection.

Updated Volume: None at the time of this update

Date: 12/12/2018 **Status:** No Further Action Requested

Author: Martin, Russell

Notes:

Received follow-up documentation and NFA letter request. Documentation confirms cleanup is complete, awaiting some final administrative documents before issuing NFA letter.

Updated Volume: None at the time of this update

Date: 12/21/2018 **Status:** Correspondence

Author: Martin, Russell

Notes:

Russell Martin sent a No Further Action letter dated December 21, 2018.

Updated Volume: None at the time of this update