General Environmental Incident Summary

	2
Incident: 5715	Notice: 5/10/2018 10am Occurred: 5/5/2018 10am
DEM Incident No:	No Further Action: 🔽
Responsible Party:	Agtegra Cooperative
County:	Emmons
Twp Rng Sec Qtr:	129 74 6
Lat Long + Method:	46.02851 -99.99643 Interpolation from map
Location Description:	201 Main Ave. W Hague ND 58542 Agtegra Cooperative
Submitted By Info:	William Spreeman
	VP Safety Environmental (Agtegra Cooperative)
	908 Lamont Street
	Aberdeen SD 57401
Received By Info:	
Contact Info:	William Spreeman
	201 Main Ave. W
	Hague ND 58542
Affected Medium:	03 - soil
Near. Occupied Bldg:	200 Feet
Type of Incident:	Tank Leak
Release Contained:	Yes
Reported to NRC:	No
Contaminant:	10-34 Fertilizer (Liquid Ag Crop Fertilizer)
Volume of Release:	750 gallons
Duration of Release:	15 minutes
Agriculture Related:	Yes
EPA Extremely Hazardous Substance:	No
Number of Fatalities:	0
Number of Injuries:	0
Cause of Incident:	
T I I (I (

The valve on tank malfunctioned causing spill / release of approximately 750 gallons of fertilizer to the drive area around the tanks - additional gravel / absorbent was added to "soak up" the free material.

Risk Evaluation:

There is no immediate risk created from the spill.

Potential Env. Impacts:

Minimal to no impact expected as a result of isolation and removal of gravel that contacted the fertilizer.

Action Taken/Planned:

The gravel (class 5 mostly) will be excavated and hauled to a licensed landfill for disposal. The excavated area will have gravel replaced.

Wastes Disposal Location:

Nearest licensed landfill

Other Agencies Involved:

Local Emergency Manager

Updates

Date: 5/10/2018 Status: Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted the surrounding area. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 5/14/2018 *Status:* Correspondence

Author: O'Gorman, Brian

Notes:

Received an email from the company contact with photos of the cleanup attached. Email and photos added to the incident folder. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 9/25/2018 Status: Inspection

Author: Stockdill, Scott

Notes:

Arrived on location 12:04 9/25/2018.

No sign of contaminants or contamination at the described location.

No follow-up is necessary.

Updated Volume: None at the time of this update