

General Environmental Incident Summary

Incident: 5779 **Notice:** 7/9/2018 0830 **Occurred:** 7/8/2018 1600

DEM Incident No: **No Further Action:**

Responsible Party: Oneok Rockies Midstream

County: Williams

Twp Rng Sec Qtr: 155 103 21

Lat Long + Method: 48.23071 -103.94570 Interpolation from map

Location Description: Stateline Gas Plant
15071 56th Street NW
Williston, ND 588011

Submitted By Info: Levi Weltikol
896 25th St SE
Sidney MT 59270

Received By Info:

Contact Info: Levi Weltikol
896 25th St SE
Sidney MT 59270

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Loss of lube oil during fire

Release Contained: Yes

Reported to NRC: No

Contaminant: Lube Oil

Volume of Release: 2 barrels

Duration of Release:

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities:

Number of Injuries:

Cause of Incident:

A storage tote failed during a fire releasing the contents inside the building. 2 bbls of lube oil left the building and impacted facility soil.

Risk Evaluation:

No immediate risk due to release of lube oil.

Potential Env. Impacts:

Impacts remained on site and were isolated to the immediate surface soils, after cleanup no environmental impacts are anticipated

Action Taken/Planned:

Spill kit was deployed to soak up any free standing liquid. Plans are being made to remove impacted facility soil.

Wastes Disposal Location:

Certified landfill- To be determined

Other Agencies Involved:

Updates

Date: 7/9/2018 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted areas not associated with an E & P location. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 6/10/2019 **Status:** Inspection

Author: Striebel, Ivana

Notes:

5/29/2019 - Onsite at 3:52 pm, hazy, west winds at ~10 mph, 82° F. Lube oil release due to fire which was mostly caused by a piece of equipment that overheated. The building was a complete loss and has since been rebuilt. There is a small amount of oil staining on the foundation of the building. The route the oil would have taken would have been through a culvert and eventually out to the stormwater pound. Found no visual evidence of staining in the ditch to the culvert or in the stormwater pound. Pictures are located in the folder. Recommend no further action.

Updated Volume: None at the time of this update

Date: 8/23/2019 **Status:** Correspondence

Author: Striebel, Ivana

Notes:

Ivana Striebel sent a No Further Action letter dated August 23, 2019.

Updated Volume: None at the time of this update