

# General Environmental Incident Summary

**Incident:** 5784      **Notice:** 7/11/2018    0900    **Occurred:** 7/10/2018    1430

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** Tuttle Farmers Elevator

**County:** Kidder

**Twp Rng Sec Qtr:** 142 74 1 SW

**Lat Long + Method:** 47.14132 -99.99935 Interpolation from map

**Location Description:** 1/2 West of City of Tuttle on Hwy 36

**Submitted By Info:** Edward Bickel  
Manager  
102 N Main  
PO Box 119  
Tuttle ND 58488

**Received By Info:**

**Contact Info:** Edward Bickel  
102 N Main St  
PO Box 119  
Tuttle ND 58488

**Affected Medium:** 09 - other

**Near. Occupied Bldg:** 0.25 Miles

**Type of Incident:** Tank Leak

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** Dyed Diesel Fuel

**Volume of Release:** 500 gallons

**Duration of Release:** 10 hours

**Agriculture Related:** No

**EPA Extremely**

**Hazardous Substance:** Unknown

**Number of Fatalities:**

**Number of Injuries:**

**Cause of Incident:**

Storm on 7/8/2018 tipped loading rack over causing problem

**Risk Evaluation:**

none

**Potential Env. Impacts:**

none

**Action Taken/Planned:**

It is in a self contained pit

**Wastes Disposal Location:**

Will need to contact health department to find out?

**Other Agencies Involved:**

NDDes, State Fire Marshal, Local Fire Department, Local Law Enforcement, Local Emergency Manager

## **Updates**

---

**Date:** 7/11/2018      **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this spill impacted areas not associated with an E & P location. Follow-up is necessary.

**Updated Volume:** None at the time of this update

---

**Date:** 7/11/2018      **Status:** Inspection

**Author:** Stockdill, Scott

**Notes:**

Arrived on location 12:54 7/11/2018.

Spill currently in progress with diking partially full. Responsible party contacted company to fix broken line. Company coming to pump it out at the time of inspection.

Responsible party was requested to give the NDDoH a call when the dike was emptied.

More follow-up is necessary.

**Updated Volume:** None at the time of this update

---

**Date:** 7/26/2018      **Status:** Inspection

**Author:** Stockdill, Scott

**Notes:**

Arrived on location 4:30 7/26/2018.

No sign of impacts outside of the dike. It appears that the spill remained on location, within the diking system.

No follow-up is necessary.

**Updated Volume:** None at the time of this update

---

**Date:** 10/4/2018      **Status:** Inspection

**Author:** Stockdill, Scott

**Notes:**

Arrived on location 10:12 10/4/2018.

No sign of remaining impacts or contaminants. Dike has been reinforced and a new dispenser system is in place.

No follow-up is necessary.

**Updated Volume:** None at the time of this update