

General Environmental Incident Summary

Incident: 5901 **Notice:** 11/8/2018 0545 **Occurred:** 11/8/2018 0545

DEM Incident No:

No Further Action:

Responsible Party: Steven calzada

County: Oliver

Twp Rng Sec Qtr: 142 83 1

Lat Long + Method: 47.14299 -101.13150 Interpolation from map

Location Description: Go north on hwy 25 from Mandan towards Center. Turn right on 30th Street. Drive for a little over 2 miles passed 19th Ave. There is farming equipment near the entrance to the accident. The spill is in the ditch on the east side.

Submitted By Info: Steven or Calzada
1710 W Crescent
Odessa TX 79761

Received By Info:

Contact Info: Steven Calzada
1710 W Crescent
Odessa TX 79761

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Vehicle Accident

Release Contained: No

Reported to NRC: Unknown

Contaminant: Diesel fuel

Volume of Release: 100 gallons

Duration of Release: 30 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

I laid my truck over, and the cap to the tank came off, allowing the fuel to leak out.

Risk Evaluation:

Ground is frozen, so the fuel should not soak in very deep past the surface.

Potential Env. Impacts:

Contaminate the dirt.

Action Taken/Planned:

Excavate the top soil.

Wastes Disposal Location:

Other Agencies Involved:

Local Law Enforcement

Updates

Date: 11/9/2018 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, the release was not contained. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 11/9/2018 **Status:** Correspondence

Author: DeVries, Taylor

Notes:

A third party environmental consultant has been hired for clean up. A site visit is needed next week.

Updated Volume: None at the time of this update

Date: 11/13/2018 **Status:** Inspection

Author: DeVries, Taylor

Notes:

Inspection date: 11/13/2018

Arrived on location at 1530. The GPS coordinates are correct and lead you right to the spill. The gravel road has some staining and the ditch is staked. No work has been done at the time of the inspection. Further follow up is needed to assess clean up efforts.

Photos were taken and can be found in the report folder.

Updated Volume: None at the time of this update

Date: 9/10/2019 **Status:** Inspection

Author: Nieraeth, Shawna

Notes:

9/10/2019 - Weather: Clear, sunny, approximately 65 F. Due to recent rain, the road was wet and a bit difficult to drive on. Found site as per given GPS coordinates. Stopped and walked north and south on road approximately 50 yards. Excavated area with good grass and weed growth found approximately 75 feet south of the west side approach on the east side of the road. Vegetation looked healthy on both sides of the road.

Updated Volume: None at the time of this update

Date: 9/10/2019 **Status:** No Further Action Requested

Author: DeVries, Taylor

Notes:

Vegetation has grown back nicely. No further follow up needed at this time.

Updated Volume: None at the time of this update