

General Environmental Incident Summary

Incident: 7008 **Notice:** 3/7/2019 1700 **Occurred:** 3/6/2019 1800

DEM Incident No:

No Further Action: ☒

Responsible Party: COS

County: Williams

Twp Rng Sec Qtr: 154 101 21

Lat Long + Method: 48.14546 -103.69060 Interpolation from map

Location Description: 100 ft south of Sunset Blvd. 200 ft North of Sunrise Dr. North bound lane on 48th Ave W on the asphalt.

Submitted By Info: Kenny Brown
Manager
501 48TH AVE W
WILLISTON ND 58801

Received By Info:

Contact Info: Jason Pahl
501 48TH AVE W
Williston ND 58801

Affected Medium: 09 - other

Near. Occupied Bldg: 300 Feet

Type of Incident: Broken Hydraulic hose

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Mobile DTE 10 32

Volume of Release: 25 gallons

Duration of Release: 10 minutes

Agriculture Related: No

**EPA Extremely
Hazardous Substance:** No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Drive line to the 784 transmission failed and hit a hydraulic hose and ruptured it.

Risk Evaluation:

None

Potential Env. Impacts:

None

Action Taken/Planned:

Floor dry was used to absorb the fluid. The area was then pressure washed with hot water and sucked up with a vacuum truck. Williston Fire Department and The City of Williston were present.

Wastes Disposal Location:

Secure 13 Mile Corner Facility

Other Agencies Involved:

Local Fire Department, Local Law Enforcement, Local Emergency Manager, City Of Williston

Updates

Date: 3/7/2019 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Notes:

Release on roadway. Follow-up is required.

Updated Volume: None at the time of this update

Date: 3/7/2019 **Status:** Inspection

Author: Torgerson, Brad

Notes:

On 3/7/2019 at 9:00am - Cloudy and 5 Degrees F - I visited a site on the east side of the asphalt paved 48th Ave NW, just 60 yards south of Sunset Blvd., in Williston. A spill of hydraulic oil onto the pavement in this area was reported on the previous day. According to a representative of Castle Oilfield Service (COS) whom I met with at the site, the spill area was washed with water and vacuumed up using a vac truck on the night of 3/6/2019. The representative indicated some of the wash water entered a storm sewer inlet structure on the east side of 48th Ave NW, but all of the fluid that entered the storm sewer was recovered with the vac truck and none of the wash water exited the storm sewer outlet pipe. A stained area (approximately 50 feet S. to N. and 20 feet E. to W), and ice were noted on the surface of the pavement on the north bound lane of 48th Ave NW.

Updated Volume: None at the time of this update

Date: 3/12/2020 **Status:** Inspection - No Action Required

Author: Lund, Dylan

Notes:

Arrived 2:20pm 3/12/2020

No sign of any remaining oil on roadway. No follow-up required. No photos taken.

Updated Volume: None at the time of this update