

Updates

Date: 3/11/2019 **Status:** Reviewed - Follow-up Required

Author: Martin, Russell

Notes:

Release due to pipeline leak, at a non-E&P exempt facility, according to the report. Follow-up is necessary. Received photo of incident from contact person.

Updated Volume: None at the time of this update

Date: 3/13/2019 **Status:** Inspection

Author: DeVries, Taylor

Notes:

Inspection date: 3/13/2019

Arrived on location at 1500. Met with an employee and he showed me where the release occurred. There was some staining on the ground near the end of the pipe. Two "pigs" were also by the pipe. There was a tin bucket that had contaminated soil in it. Photos were taken and can be found in the report folder. Another investigation should be made to see if the contaminants went off location.

Updated Volume: None at the time of this update

Date: 2/25/2020 **Status:** Correspondence - Vegetation Check

Author: Martin, Russell

Notes:

Based on photo of initial release supplied by RP and inspection conducted on 3/18/2019, conduct vegetation check summer of 2020 to evaluate offsite pipeline ROW and associated agricultural field within release area.

Updated Volume: None at the time of this update

Date: 7/31/2020 **Status:** Inspection - No Action Required

Author: Martin, Russell

Notes:

7/16/2020 at 11:37, on location. Met with personnel for the RP. Field impacted during incident has not been cultivated, currently fallow. However, weeds growing between compressor station fence and field boundary appear uniform, and scattered weeds in field do not appear affected by incident. No further follow-up needed at this time.

Updated Volume: None at the time of this update