

Updates

Date: 5/16/2019 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill involved a large amount of material lost. Follow-up is necessary to ensure proper cleanup.

Updated Volume: None at the time of this update

Date: 5/23/2019 **Status:** Inspection

Author: Crowdus, Kory

Notes:

On location 5/23/2019, at 11:33am. Met with company contact. The release was approximately 200 yards east of the pipeline access road. Silt fences are in place to contain material. Vac trucks have been at the site sucking up material. Minimal material remains at the site. No further follow-up is required.

Updated Volume: None at the time of this update