General Environmental Incident Summary

Incident: 8079 Notice: 5/20/2019 **Occurred:** 5/18/2019

DEM Incident No: No Further Action: ✓

Responsible Party: **CHS** Transportation

County: Bottineau Twp Rng Sec Qtr: 161 83 20

Lat Long + Method: 48.76297 -101.45860 Interpolation from map Location Description: Hwy 5 approx. 1 and three guarter miles east from Mohall.

Submitted By Info: Eric Pearson

CHS

4115 27th Ave N

Grand Forks ND 58203

Received By Info:

Contact Info: Eric Pearson

4115 27th Ave N

Grand Forks ND 58203

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Vehicle Accident

Release Contained: Yes Reported to NRC: Unknown Contaminant: Oil from Truck

Volume of Release: 10 gallons 1 minutes **Duration of Release:** Agriculture Related: Yes

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: Number of Injuries: Cause of Incident:

Driver suffered Seizure while driving and left road hitting approach and cracking oil pan releasing oil.

Risk Evaluation:

minimal. some oil in water along ditch. minimal water in ditch.

Potential Env. Impacts:

very low. most material has been collected. remaining will be collected asap.

Action Taken/Planned:

Bulk of material contained with spill pads and booms. Strata Corp Env. will be on site cleaning up remaining material.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 5/20/2019 Status: Reviewed - Follow-up Required

Author: Martin, Russell

Notes:

Release due to a vehicle accident, on a roadway according to the report. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 5/22/2019 Status: Inspection

Author: O'Gorman, Brian

Notes:

Arrived at the location at 11:14. 56 degrees F, Cloudy, Northeast wind 10-20 mph. Observed the area and took photos. You could see where the tire track went into the ditch then hit the approach and stopped on the east side of the approach. Oil absorbent booms had been placed in some standing water east of the approach. Booms should be replaced. More follow-up needed. Photos added to the incident folder.

Updated Volume: None at the time of this update

Date: 8/7/2019 Status: Inspection

Author: O'Gorman, Brian

Notes:

Arrived on location at 10:50. Observed site and took photos. Did not notice any areas of dead and/or stressed vegetation. No further follow-up needed at this time. Photos added to the incident folder.

Updated Volume: None at the time of this update