



## **Updates**

---

**Date:** 7/17/2019      **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Notes:**

According to the report, 80 gallons of transformer oil (non-PCB) was released from a transformer. Further follow-up needed.

**Updated Volume:** None at the time of this update

---

**Date:** 7/17/2019      **Status:** Correspondence

**Author:** O'Gorman, Brian

**Notes:**

Received several emails from the MDU contact with photos to show the incident location and cleanup of the site. Photos appear to show a complete cleanup of the area. Awaiting photo of transformer and non-PCB label. More follow-up needed. Photos and emails added to the incident folder.

**Updated Volume:** None at the time of this update

---

**Date:** 7/25/2019      **Status:** Correspondence

**Author:** Striebel, Ivana

**Notes:**

7/25/2019 - added a photo to the incident folder. This photo shows the name plate of the transformer and indicates that this is a non-PCB transformer release. Further action needed.

**Updated Volume:** None at the time of this update

---

**Date:** 2/9/2021      **Status:** Correspondence - More Follow-up Required

**Author:** Suess, Bill

**Notes:**

This spill involves non-PCB mineral oil. The Spill Investigation Program will retain oversight.

**Updated Volume:** None at the time of this update

---

**Date:** 3/4/2021      **Status:** Inspection - No Action Required

**Author:** Suess, Bill

**Notes:**

Inspected the site on 3/4/2021. The area around the transformer has been scraped up and no signs of impacts were observed. No further action is warranted.

**Updated Volume:** None at the time of this update