

Updates

Date: 7/12/2019 **Status:** Reviewed - No Action Required

Author: O'Gorman, Brian

Notes:

According to the report, 50 gallons of bentonite water was released during boring operations. Report says release was contained within borehole and vacuumed out immediately. No further follow-up should be needed at this time due to inert composition of released material.

Updated Volume: None at the time of this update