

General Environmental Incident Summary

Incident: 9222

Notice: 9/6/2019

Occurred: 9/6/2019

DEM Incident No:

No Further Action:

Responsible Party: Unknown

County: Cass

Twp Rng Sec Qtr: 138 49 6

Lat Long + Method: 46.80002 -96.91396 Interpolation from map

Location Description: 748 CATHY DR W
WEST FARGO, ND 58078

Submitted By Info: CJ Erickson
4100 32nd Ave S
FARGO ND 58104

Received By Info: ND - North Dakota Erickson

Contact Info: CJ Erickson
n/a
n/a ND 58078

Affected Medium: 03 - soil

Near. Occupied Bldg: 30 Feet

Type of Incident: Utility transformer leak

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Transformer mineral oil, non-PCB per manufacture stamp on transformer

Volume of Release: 50 gallons

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Contractor digging hit underground power line breaking bushing causing less than 10 gallons of oil to leak. . CCEC location number 106-062-2850, coop number# 24087

Risk Evaluation:

None

Potential Env. Impacts:

none, oil contained and cleaned up.

Action Taken/Planned:

Oil was contained in transformer basement. Crew sucked up the oil and cleaned up basement with oil absorbent pads. Hold oil and clean-up material will be held until oil test verifies this is non-PCB oil.

Wastes Disposal Location:

Upon receipt of transformer oil testing, any non-PCB dirt and spill clean-up material will be disposed of at a land fill. If testing identifies the presence of PCB's measures will be taken to ensure disposal of all product is done through Clean Harbors Environmental, Inc., Coffeyville, KS.

Other Agencies Involved:

Updates

Date: 9/6/2019 **Status:** Reviewed - Assigned to NDDEQ Division

Author: Martin, Russell

Notes:

Release from electrical equipment due to mineral oil leak. Assigned to Division of Waste Management.

Updated Volume: None at the time of this update

Date: 9/9/2019 **Status:** Correspondence

Author: Striebel, Ivana

Notes:

9/9/2019 - Received incident photos and requested lab results. This was a release of 50 gallons and will need a future site visit, further action needed.

Updated Volume: None at the time of this update

Date: 10/29/2019 **Status:** Correspondence - More Follow-up Required

Author: Striebel, Ivana

Notes:

10/9/2019 - Received lab results from responsible party. I will coordinate a site inspection. Further action needed.

Updated Volume: None at the time of this update

Date: 2/9/2021 **Status:** Correspondence - More Follow-up Required

Author: Suess, Bill

Notes:

This spill involves non-PCB mineral oil. The Spill Investigation Program will retain oversight.

Updated Volume: None at the time of this update

Date: 4/30/2021 **Status:** Inspection - No Action Required

Author: Suess, Bill

Notes:

Inspected the site on 4/26/2021. No adverse environmental impacts, associated with this release, were observed. No further action is warranted.

Updated Volume: None at the time of this update