

General Environmental Incident Summary

Incident: 9249 **Notice:** 9/24/2019 1545 **Occurred:** 9/21/2019 1300

DEM Incident No:

No Further Action:

Responsible Party: Andeavor Logistics

County: Williams

Twp Rng Sec Qtr: 158 96 13

Lat Long + Method: 48.51639 -103.03580 Interpolation from map

Location Description: Murex Elmer Olaf 13-24H Station near Tioga

Submitted By Info: Rose Salazar
Environmental Professional
6 Centerpoint Drive
La Palma CA 90623

Received By Info:

Contact Info: Rose Salazar
6 Centerpoint Drive
La Palma CA 90623

Affected Medium: 04 - water and soil

Near. Occupied Bldg:

Type of Incident: Truck Overfill

Release Contained: Yes

Reported to NRC: No

Contaminant: crude oil

Volume of Release: 8 barrels

Duration of Release: 15 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities:

Number of Injuries:

Cause of Incident:

While performing the loading process, the truck driver left the bleeder valve open. Crude oil was released to the ground within the secondary containment of the location tanks.

Risk Evaluation:

No immediate risks identified

Potential Env. Impacts:

No environmental impacts, release was all within containment on private property

Action Taken/Planned:

Truck driver immediately shut down operations, closed valves and contacted appropriate company authorities. No impact to wildlife or ground water. Clean up activities include absorption of oil layer on top of water and removal of waste water for oil recovery off-site. Upon further evaluation, potential soil excavation will be determined.

Wastes Disposal Location:

Solid debris disposed off site at state approved landfill and waste water sent to recycler for oil recovery.

Other Agencies Involved:

Updates

Date: 9/24/2019 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, the release of crude oil was contained to the well pad. Further follow up is needed.

Updated Volume: None at the time of this update

Date: 10/14/2019 **Status:** Inspection - No Action Required

Author: Martin, Russell

Notes:

10/9/2019 at 16:51, on location. Original report for duplicate found in OEIR database #20190927113728. Checked area next to crude oil tank loading getty boxes, at the southwest corner of the battery. No visible staining outside the secondary containment around the tank battery in this area. No further follow-up required.

Updated Volume: None at the time of this update