

General Environmental Incident Summary

Incident: 9305 **Notice:** 11/6/2019 1430 **Occurred:** 11/6/2019 0700

DEM Incident No:

No Further Action:

Responsible Party: Cudd Pressure Control

County: McKenzie

Twp Rng Sec Qtr: 151 96 20

Lat Long + Method: 47.88995 -102.98940 Interpolation from map

Location Description: Demicks Lake Plant
From Keen, ND take ND23 south to county rd 12 turn west onto cr12, Go to 113th Ave and turn south, go 1 mile turn left and go approx. .5 miles to plant on the south side of road.

Submitted By Info: Catalino Diangson
Operations Manager
4830 S 4625 E
Vernal UT 84078

Received By Info:

Contact Info: Eric Baldridge
2828 Technology Forest Blvd.
The Woodlands TX 77381

Affected Medium: 03 - soil

Near. Occupied Bldg: 1000 Feet

Type of Incident: Pump Leak

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Diesel Fuel

Volume of Release: 5 gallons

Duration of Release: 1 hours

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

The pump operator forgot to turn off the fuel pump for the burner when he shut down the pump. This resulted in the fuel running out of the burner box onto the ground.

Risk Evaluation:

None

Potential Env. Impacts:

None

Action Taken/Planned:

Soil excavation with a super vac truck from a third party.

Third party info:

Stateline Energy Service Solutions.

5061 139th Ave NW

Williston, ND 58801

Stateline Contact:

Ron Johnson (701)580-5520

Wastes Disposal Location:

Secure Energy
Thirteen mile corner

Other Agencies Involved:

Updates

Date: 11/14/2019 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

According to the report, 5 gallons of diesel fuel was released. More follow-up needed.

Updated Volume: None at the time of this update

Date: 11/19/2019 **Status:** Inspection - No Action Required

Author: O'Gorman, Brian

Notes:

Arrived on location at 14:30. 43 degrees F, Partly Cloudy, Calm. Drove to the GPS point provided in the report and took photos. Did not notice any petroleum stained soils south of the road. Area was either parking lot or newly filled pipeline right-of-way. No further follow-up needed at this time. Photos added to the incident folder.

Updated Volume: None at the time of this update