



## **Updates**

---

**Date:** 2/26/2020      **Status:** Reviewed - Follow-up Required

**Author:** DeVries, Taylor

**Notes:**

According to the incident summary, this spill impacted the surrounding area. Follow-up is necessary.

**Updated Volume:** None at the time of this update

---

**Date:** 2/27/2020      **Status:** Inspection - More Follow-up Required

**Author:** Stockdill, Scott

**Notes:**

Arrived on location 2:19 2/27/2020.

According to the responsible party, the leak occurred in the housing of the pump where it filled up the housing of the pump and overflowed onto the concrete pad. It was determined that the release involved 1300 gallons of #1 diesel and 25 gallons of #2 diesel. A majority of the released diesel was contained to the pad, however, some did migrate off of the pad and onto the gravel driveway belonging to NorthStar CO-OP. Some of the impacted gravel was scraped up and placed in collection area. Responsible party has been given the contact information for the UST program and for the AST insurance program.

Follow-up is necessary to ensure proper cleanup.

**Updated Volume:** 1300 gallons

---

**Date:** 5/8/2020      **Status:** Inspection - No Action Required

**Author:** Stockdill, Scott

**Notes:**

Arrived on location 5/7/2020.

No sign of contamination or contaminants at the time of inspection. Check with Tank insurance program to determine if any other work is necessary with their program.

No onsite follow-up is necessary.

**Updated Volume:** None at the time of this update