Oil Field Environmental Incident Summary

Incident: 20191111172530   **Notice:** 11/11/2019   17:25   **Occurred:** 11/9/2019   14:40

Responsible Party:	Nine Point Energy, LLC
Well Operator:	NINE POINT ENERGY, LLC
Well Name:	Erickson North 155-102-26 SWD
Field Name:	SQUIRES
Well File #:	90458
Facility ID #:	
County:	WILLIAMS
Twp Rng Sec Qtr:	155 102 26 NW NE
Location Description:	
Submitted By:	Tracey Fallang
Received By:	
Contact Info:	Cullin Johnson
	1001 17th Sreet, Suite 1400
	Denver CO 80202
Affected Medium:	Well/Facility Soil
General Land Use:	Well/Facility Site
Near. Occupied Bldg:	2100 Feet
Nearest Water Well:	2100 Feet
Type of Incident:	Pipeline Leak
Release Contained:	Yes - On Facility Site
Reported to NRC:	No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	20	Barrels	20	Barrels		
Other						

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

Low - spill was contained on location.

Areal Extent:

Spill was not contained within containment but was contained on the location.

Potential Env. Impacts:

Impacts if not discovered quickly could be impacts to surface/ground water.

Action Taken/Planned:

The emergency shut down was pushed immediately upon discovery of the leak. Contaminated soil has been vac'd/excavated and hauled to disposal. The line that parted is new and Henry Hill Oilfield Services, the contactor that installed the line, is taking the failed pipe coupler to the manufacturer for testing to determine the cause of failure.

Wastes Disposal Location:

Wastes were handled by Henry Hill via using a vac truck and hauling to Secure disposal. Waiting on further input from Henry Hill and Nine Point field personnel on conclusion of cleanup activities.

Other Agencies Involved:

Jessica Gilkey with NDIC was notified by Henry Hill

Updates

Date: 11/12/2019   *Status:* Reviewed - Assigned to Other Agency   *No Further Action:* ☑

Author: O'Gorman, Brian

Notes:

Release, due to a pipeline leak, was contained on the site according to the report. NDIC retains oversight.

Updated Volumes and Contaminant   None at the time of this update