Oil Field Environmental Incident Summary

Incident: 20170116165111 Notice: 1/16/2017 16:51 Occurred: 1/16/2017 13:00

Responsible Party: WHITING OIL AND GAS CORPORATION Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: SOLBERG 21-2H CTB

Field Name: RAY

Well File #:

Facility ID #: 226189-01
County: WILLIAMS

Twp Rng Sec Qtr: 156 97 2 NW NW

Location Description:

Submitted By: Brian Wurm

Received By:

Contact Info: Brian Wurm

1700 BROADWAY STE 2300

DENVER CO 80290

Affected Medium: Topsoil
General Land Use: Cultivated
Near. Occupied Bldg: 0.5 Mile
Nearest Water Well: 0.5 Mile
Type of Incident: Treater Popoff

Release Contained: No Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnitsOil0.5Barrels0.5Barrels0.5barrels

Brine Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 1/25/2017 Written Report Recd: 2/2/2017

Risk Evaluation:

None noted. Release stopped and cleanup in progress.

Areal Extent:

Approximately 30' by 10' to the east off location.

Potential Env. Impacts:

None noted. Release stopped and cleanup in progress.

Action Taken/Planned:

Impacted snow offsite will be pulled back onto location and disposed of at the Secure Disposal facility.

Wastes Disposal Location:

Secure Disposal facility

Other Agencies Involved:

Updates

Date: 1/17/2017 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the report, the release was not contained to the well pad. Further follow up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 2/1/2017 Status: Inspection No Further Action: ✓

Author: Stockdill, Scott

Notes:

Arrived on location 12:59, 2/1/2017.

Spray from tank to the SE of the pad. Materials in the impacted area have been scraped up and removed.

Follow-up in spring to ensure vegetation regrowth.

Updated Volumes and Contaminant None at the time of this update

Date: 3/30/2017 Status: Inspection No Further Action: ✓

Author: Stockdill, Scott

Notes:

Arrived on location 1:38, 3/30/2017.

Small amount of remaining oil entrained in vegetation off of east side of the well pad. No sign of oil in nearby standing water.

No follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update