Oil Field Environmental Incident Summary

Incident: 20170118131558 Notice: 1/18/2017 13:15 Occurred: 1/17/2017 13:15

Responsible Party: Condor Petroleum, Inc.

Well Operator: CONDOR PETROLEUM, INC.

Well Name: KJELSHUS 1
Field Name: STONEVIEW

Well File #: 13259

Facility ID #:

County: DIVIDE

Twp Rng Sec Qtr: 160 95 2 SE SE

Location Description: Wellsite

Submitted By: Denise Gustafson

Received By:

Contact Info: Denise Gustafson

216 16TH STREET SUITE 1750

DENVER CO 80202

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: 2 Mile Nearest Water Well: 2 Mile

Type of Incident: Treater Popoff

Release Contained: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine

Other 1 Gallons

Oth Rel. Contaminant: 1/2 gallon of mist from flare pit

Date Inspected:

Clean Up Concluded: 1/19/2017
Written Report Recd: 2/9/2017

Risk Evaluation:

None

Areal Extent:

15' - 20' north of flare pit **Potential Env. Impacts:**

None

Action Taken/Planned:

Minimal clean up required

Wastes Disposal Location:

Non applicable

Other Agencies Involved:

Updates

Date: 1/19/2017 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the report the release was not contained. Further follow-up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 1/23/2017 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: Nieraeth, Shawna

Notes:

Unable to locate site. I would recommend another attempt to locate it after spring breakup.

Updated Volumes and Contaminant None at the time of this update

Date: 1/31/2017 Status: Inspection No Further Action: ✓

Author: Stockdill, Scott

Notes:

Arrived on location 1/31/2017.

Minor impacts to areas north of the flare. No risks associated with spill.

No follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update