

Oil Field Environmental Incident Summary

Incident: 20170318190755 **Notice:** 3/18/2017 19:07 **Occurred:** 3/17/2017 14:20

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: EN-WEYRAUCH A-154-93-1720H-3-6

Field Name: ROBINSON LAKE

Well File #:

Facility ID #: 224368-01

County: MOUNTRAIL

Twp Rng Sec Qtr: 154 93 17 NE NE

Location Description:

Submitted By: Troy Brunsell

Received By:

Contact Info: Troy Brunsell
1501 MCKINNEY
HOUSTON TX 77010

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 1.5 Mile

Nearest Water Well: 1.5 Mile

Type of Incident: Equipment Failure

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3.6	Barrels			3.6	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 4/19/2017

Written Report Recd: 5/2/2017

Risk Evaluation:

No immediate risk to report at this time

Areal Extent:

Potential Env. Impacts:

Fine mist of oil covered production equipment, snow and location soil on location.

Action Taken/Planned:

All wells on location have been shut in, treater has been isolated / drained down with pressure bled off. Repair notifications have been submitted, equipment will remain isolated until repairs are

Wastes Disposal Location:

Approved waste facility

Other Agencies Involved:

Other Agencies Involved:

Updates

Date: 3/20/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to equipment failure, was contained to the constructed well site according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update