

Oil Field Environmental Incident Summary

Incident: 20170525135832 **Notice:** 5/25/2017 13:58 **Occurred:** 5/24/2017 14:27

Responsible Party: SCOUT ENERGY MANAGEMENT LLC

Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: MOSSER 30-26H

Field Name: T. R.

Well File #: 13581

Facility ID #:

County: BILLINGS

Twp Rng Sec Qtr: 141 101 26 SW SW

Location Description:

Submitted By: Rebecca Sample

Received By:

Contact Info: Rebecca Sample
4901 LBJ FREEWAY, STE 300
DALLAS TX 75244

Affected Medium: Topsoil

General Land Use: Badlands Terrain

Near. Occupied Bldg: 4 Mile

Nearest Water Well: 2 Mile

Type of Incident: Fire

Release Contained: Unknown

Reported to NRC: No

Spilled	Units	Recovered	Units	Followup	Units
----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other

Oth Rel. Contaminant: N/A

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

N/A

Areal Extent:

4 foot x 6 foot

Potential Env. Impacts:

N/A

Action Taken/Planned:

Steam truck was on location. The steam truck put the fire out.

Wastes Disposal Location:

N/A

Other Agencies Involved:

N/A

Updates

Date: 5/26/2017 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: O'Gorman, Brian

Notes:

According to the report, topsoil was affected by a fire and it was unknown if the release was contained. Further follow-up needed.

Updated Volumes and Contaminant None at the time of this update

Date: 6/29/2017 **Status:** Inspection

No Further Action:

Author: Martin, Russell

Notes:

6/26/2017 at 18:15, on location. Flare located along western edge of wellpad surrounded by grasslands, with some shorter vegetation directly adjacent to flarepit further to the west, but no staining visible, whatever damage was done by the fire appears to have naturally attenuated. No further follow-up required at this time.

Updated Volumes and Contaminant None at the time of this update