Oil Field Environmental Incident Summary

Responsible Party: HENRY HILL OIL SERVICES, LLC
Well Operator: HENRY HILL OIL SERVICES, LLC
Well Name: NORTH DICKINSON SWD 1

Field Name: RUSSIAN CREEK

Well File #: 6224

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 141 96 11

Location Description:

Submitted By: Matt Azure

Received By:

Contact Info: Matt Azure

120 26TH STREET EAST

SUITE 200

WILLISTON ND 58801

Affected Medium: Topsoil

General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Other

Release Contained: Yes - Within Dike

Reported to NRC: Yes

SpilledUnitsRecoveredUnitsFollowupUnits4Barrels4Barrels5barrels

Brine Other

Oil

Oth Rel. Contaminant: oil from oil holding tank

Date Inspected:

 Clean Up Concluded:
 7/21/2017

 Written Report Recd:
 7/27/2017

Risk Evaluation:

soil

Areal Extent:

Potential Env. Impacts:

oil on suface of soil

Action Taken/Planned:

Badger hydro vac called to site to remove all spilled oil on the soil. New locks and caps put in place.

Wastes Disposal Location:

horizon solid waste

Other Agencies Involved:

Updates

Date: 7/24/2017 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: O'Gorman, Brian

Notes:

Release was contained within the diking according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update