## Oil Field Environmental Incident Summary

Incident: 20170916162525 Notice: 9/16/2017 16:25 Occurred: 9/16/2017 10:40

Responsible Party:EOG RESOURCES, INC.Well Operator:EOG RESOURCES, INC.Well Name:VAN HOOK 46-3626H

Field Name: PARSHALL Well File #: 31206

Facility ID #:

County: MOUNTRAIL
Twp Rng Sec Qtr: 152 91 36

Location Description:

Submitted By: Hunter Ball

Received By:

Contact Info: Hunter Ball

600 17TH ST STE 1000N

DENVER CO 80202

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnitsOil20Barrels20Barrels20barrels

Brine Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 9/16/2017 Written Report Recd: 12/29/2017

Risk Evaluation:

N/A

Areal Extent:

Potential Env. Impacts:

N/A

Action Taken/Planned:

All liquids were sucked up with a vac truck.

Wastes Disposal Location:

The oil was clean enough that it was returned into the tanks within the tank battery on location.

Other Agencies Involved:

## **Updates**

Date: 9/18/2017 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Martin, Russell

Notes:

Release due to valve/piping connection leak, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update