

Oil Field Environmental Incident Summary

Incident: 20170918160809 **Notice:** 9/18/2017 16:08 **Occurred:** 9/18/2017 09:00

Responsible Party: LIME ROCK RESOURCES III-A, L.P.

Well Operator: LIME ROCK RESOURCES III-A, L.P.

Well Name: HARRY STROH 2-8-5H-143-96

Field Name: FAYETTE

Well File #: 26079

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 143 96 8

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Info:
Robyn Espinoza
1111 BAGBY, SUITE 4600
HOUSTON TX 77002

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Barrels	30	Barrels	30	barrels
Brine	10	Barrels	10	Barrels	10	barrels
Other	10	Barrels	10	Barrels	10	barrels

Oth Rel. Contaminant: Oil, produced water and rain water

Date Inspected:

Clean Up Concluded: 9/30/2017

Written Report Recd: 10/3/2017

Risk Evaluation:

Contaminated surface materials

Areal Extent:

All product was contained in the berm that is constructed around the well head.

Potential Env. Impacts:

Contaminated surface materials

Action Taken/Planned:

MBI was dispatched to recover all standing fluids, B&B will wash down the equipment. A visual inspection will be done and additional materials will be removed if necessary.

Wastes Disposal Location:

Chimney Butte if needed

Other Agencies Involved:

Updates

Date: 9/19/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release due to stuffing box leak remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update