

Oil Field Environmental Incident Summary

Incident: 20170921190122 **Notice:** 9/21/2017 19:01 **Occurred:** 9/21/2017 14:00

Responsible Party: ENERPLUS RESOURCES USA CORPORATION

Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: ZANE 32-24H

Field Name: MCGREGORY BUTTES

Well File #: 18221

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 148 93 32 SE SW

Location Description:

Submitted By: Joey Sheeley

Received By:

Contact Info:
 Josh Ruffo
 US BANK TOWER
 950 17TH ST STE 2200
 DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	15	Barrels			0	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 9/22/2017

Written Report Recd: 9/25/2017

Risk Evaluation:

No immediate risks.

Areal Extent:

Potential Env. Impacts:

No impacts; will be cleaned up immediately.

Action Taken/Planned:

Clean-up crew is on the way to the location.

Wastes Disposal Location:

Secure Energy Services Disposal Facility.

Other Agencies Involved:

Bureau of Land Management - Dickinson
 Bureau of Indian Affairs - New Town
 MHA Energy

Updates

Date: 9/22/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release due to stuffing box leak remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update