

Oil Field Environmental Incident Summary

Incident: 20170922090115 **Notice:** 9/22/2017 09:01 **Occurred:** 9/21/2017 09:30

Responsible Party: DENBURY ONSHORE, LLC
Well Operator: DENBURY ONSHORE, LLC
Well Name: FEDERAL WALLER 14-26H
Field Name: CEDAR HILLS
Well File #: 14177
Facility ID #:
County: SLOPE
Twp Rng Sec Qtr: 133 106 26
Location Description:
Submitted By: Mark VanGrinsven
Received By:
Contact Info: Mark VanGrinsven
 5320 LEGACY DR
 PLANO TX 75024-3127

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg: 1 Mile
Nearest Water Well: 1 Mile
Type of Incident: Valve/Piping Connection Leak
Release Contained: Yes - Within Dike
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	103	Barrels	100	Barrels	100	barrels

Brine
Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 10/24/2017

Written Report Recd: 11/2/2017

Risk Evaluation:

none

Areal Extent:

Potential Env. Impacts:

none

Action Taken/Planned:

The line was Isolated and standing fluids were recovered. Impacted soils will be removed.

Wastes Disposal Location:

LMS

Other Agencies Involved:

Updates

Date: 9/22/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release due to valve/piping connection leak remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update