

Oil Field Environmental Incident Summary

Incident: 20170922091838 **Notice:** 9/22/2017 09:18 **Occurred:** 9/21/2017 10:15

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: HADLEY 9 SWD 16

Field Name: CEDAR HILLS

Well File #: 13818

Facility ID #:

County: BOWMAN

Twp Rng Sec Qtr: 131 106 9

Location Description:

Submitted By: Mark VanGrinsven

Received By:

Contact Info: Mark VanGrinsven
5320 LEGACY DR
PLANO TX 75024-3127

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 2500 Feet

Nearest Water Well: 2500 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	94	Barrels	92	Barrels	94	barrels
Other						

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 9/22/2017

Written Report Recd: 11/2/2017

Risk Evaluation:

none

Areal Extent:

Potential Env. Impacts:

none

Action Taken/Planned:

The line was isolated and the standing fluids were recovered. The impacted area will be treated with a Biocal-water mixture.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 9/25/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Schiermeister, Robin

Notes:

Release, due to a valve/connection leak, remained on the well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update