## Oil Field Environmental Incident Summary

Incident: 20171110164529 Notice: 11/10/2017 16:45 Occurred: 11/10/2017 15:00

Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: J.M. HALL 1-19H

Field Name: MCGREGORY BUTTES

**Well File #:** 18017

Facility ID #:

County: DUNN

**Twp Rng Sec Qtr:** 148 93 19

**Location Description:** 

**Submitted By:** Joey Sheeley

Received By:

Contact Info: Josh Ruffo

**US BANK TOWER** 

950 17TH ST STE 2200 DENVER CO 80202

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

**Brine** 

Other 5 Barrels 0 barrels

Oth Rel. Contaminant: Emulsions: mix of oil and production water

Date Inspected:

**Clean Up Concluded:** 11/14/2017 **Written Report Recd:** 11/17/2017

Risk Evaluation:

None

Areal Extent:

Potential Env. Impacts:

None

Action Taken/Planned:

One-off incident; gasket will be replaced

Wastes Disposal Location:

Secure Energy Services disposal facility

Other Agencies Involved:

BLM, BIA, MHA Energy, TAT Environmental

## **Updates**

Date: 11/14/2017 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the release of emulsion was contained to the well pad. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update