

Oil Field Environmental Incident Summary

Incident: 20180106150942 **Notice:** 1/6/2018 15:09 **Occurred:** 1/6/2018 10:00

Responsible Party: CLR

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: COLUMBIA 4-5H

Field Name: DOLLAR JOE

Well File #: 24005

Facility ID #:

County: WILLIAMS

Twp Rng Sec Qtr: 155 97 5 LO T1

Location Description: 100 bbls untreated freshwater ran down ditch. 100 bbls untreated freshwater on location. Landowner notified

Submitted By: chansy wolff

Received By:

Contact Info: chansy wolff
PO BOX 268870
OKLAHOMA CITY OK 73126

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other	200	Barrels	200	Barrels	200	barrels
--------------	-----	---------	-----	---------	-----	---------

Oth Rel. Contaminant: untreated freshwater

Date Inspected:

Clean Up Concluded: 1/11/2018

Written Report Recd: 1/23/2018

Risk Evaluation:

no risk involved

Areal Extent:

2ft by 1/2 mile

Potential Env. Impacts:

no impact

Action Taken/Planned:

landowner was fine with leaving the water on his land

Wastes Disposal Location:

no

Other Agencies Involved:

Updates

Date: 1/8/2018 **Status:** Reviewed - Follow-up Required **No Further Action:** ☒

Author: Crowdus, Kory

Notes:

Release of freshwater, according to the report. Follow-up required to ensure it was only freshwater.

Updated Volumes and Contaminant None at the time of this update

Date: 1/12/2018 **Status:** Inspection **No Further Action:** ☒

Author: Schiermeister, Robin

Notes:

Arrived at 16:07 on 1-8-2018. Temperatures were in the 20's and it was cloudy. The release went east, off the well pad. It then extended downhill north until the ditch. The soil underneath the now frozen ice sheet has been stripped away of its vegetation. An inspection will be needed in the spring to determine if vegetation is regrowing.

Updated Volumes and Contaminant None at the time of this update

Date: 8/29/2019 **Status:** Correspondence - Vegetation Check **No Further Action:** ☒

Author: Suess, Bill

Notes:

The RP has been contacted to request verification of remediation at the site. Once the documents are reviewed the site will be revisited to assure proper revegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 7/23/2020 **Status:** Inspection - No Action Required **No Further Action:** ☒

Author: Suess, Bill

Notes:

Inspected the site on 7/21/2020. No adverse environmental impacts associated with this incident were observed. The vegetation appeared healthy and consistent with the surrounding area. No further action is warranted.

Updated Volumes and Contaminant None at the time of this update