

Oil Field Environmental Incident Summary

Incident: 20180106151218 **Notice:** 1/6/2018 15:12 **Occurred:** 1/5/2018 13:45

Responsible Party: NEWFIELD PRODUCTION COMPANY
Well Operator: NEWFIELD PRODUCTION COMPANY
Well Name: LOST BRIDGE FEDERAL 148-96-9-4-3H
Field Name: LOST BRIDGE
Well File #: 32734
Facility ID #:
County: DUNN
Twp Rng Sec Qtr: 148 96 9 SW SW
Location Description:
Submitted By: Tim Eaton
Received By:
Contact Info: Tim Eaton
 24 WATERWAY SQUARE PL, STE 100
 THE WOODLANDS TX 77380

Affected Medium: Topsoil
General Land Use: Badlands Terrain

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Other
Release Contained: No
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Gallons	30	Gallons		

Brine
Other

Oth Rel. Contaminant:
Date Inspected:
Clean Up Concluded:
Written Report Recd:

Risk Evaluation:
 None, oil fell mostly onto snow.

Areal Extent:
 50' x 300'

Potential Env. Impacts:
 None, some trees were slightly misted but not enough to harm them.

Action Taken/Planned:
 A hydro vac truck was used to suck up the contaminated snow where it could be reached. Roustabout hands used snow shovels to scrape the contaminated snow into a pile where the hydro vac truck could reach.

Wastes Disposal Location:
 The contaminated snow was taken to Secure disposal in Keene.

Other Agencies Involved:
 North Dakota Department of Health

Updates

Date: 1/8/2018 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Crowdus, Kory

Notes:

Release impacted areas off location. Follow-up is required.

Updated Volumes and Contaminant None at the time of this update

Date: 1/10/2018 **Status:** Inspection **No Further Action:**

Author: Washek, Sandi

Notes:

Arrived on-site at 9:05am; weather was partly sunny with winds out of the SW at 5 miles/hr., temperature of 23 degrees F.

The location of the impacted area is to the north and north west of the flare, on a steep wooded hillside in badlands terrain. GPS N47.64899 W102.92721 The area impacted is about 50 wide by about 300 feet long. A good amount of the area is a steep grade wooded hillside. The impacted snow has been removed where access was possible by hand tools and buckets. There is a visible light mist on the trees and on the top of some snow, where assess is limited due to terrain. Will need to contact the company to see what additional cleanup they have planned for the area.

Additional follow-up needed.

Updated Volumes and Contaminant

Oil		Salt Water		Other	
30.00	gallons				
Other Contaminant					

Date: 7/23/2018 **Status:** No Further Action Requested **No Further Action:**

Author: Washek, Sandi

Notes:

Arrived onsite at 8:58am. Weather was sunny with wind out of the NW at 5 miles/hr. Temperature 62 degrees F.

The area of impact was a group of trees on a steep slope north of the flare. The trees had been sprayed with a light mist of oil back in January. A number of the trees directly next to the flare appear to have been burned at some time, but over all, the ground vegetation, trees and shrubs are in good shape. Photos taken and added to incident folder.

No additional follow-up needed.

Updated Volumes and Contaminant None at the time of this update

Date: 8/2/2018 **Status:** Correspondence

No Further Action:

Author: Washek, Sandi

Notes:

Sandi Washek sent a No Further Action letter dated August 2, 2018.

Updated Volumes and Contaminant None at the time of this update